



IndustrialPro™ and MobilityPro™ Gateway Wireless Modems

BT Series Firmware Release Notes
Version 3.8.12

April 2012

IndustrialPro™ and MobilityPro™ Gateway Wireless Modems

BT Series Firmware Release Notes

No part of this publication, or any software included with it, may be reproduced, stored in a retrieval system or transmitted in any form or by any means, including photocopying, electronic, mechanical, recording or otherwise, without the prior written permission of the copyright holder.

Sixnet, Inc. (Sixnet) provides this document as is, without warranty of any kind either expressed or implied including, but not limited to, the implied warranties of merchantability and fitness for a particular purpose. Sixnet may make changes of improvements in the equipment, software or specifications described in this document at any time and without notice. These changes may be incorporated in new releases of this document.

This document may contain technical inaccuracies or typographical errors. Sixnet and its subsidiaries waive responsibility for any labor, materials or costs incurred by any person or party as a result of using this document.

Sixnet and any of its subsidiaries or other affiliates shall not be liable for any damages (including, but not limited to, consequential, indirect or incidental, special damages, or loss of profits or data) even if they were foreseeable and Sixnet has been informed of their potential occurrence arising out of or in connection with this document or its use.

Computer Software Copyrights

The Sixnet products described in this manual include copyrighted Sixnet computer programs stored in semiconductor memories or other media. Laws in Canada, the United States and other countries preserve for Sixnet certain rights for copyrighted computer programs, including the exclusive right to copy or reproduce in any form the copyrighted computer program. Accordingly, any copyrighted Sixnet computer programs contained in the Sixnet products described in this manual may not be copied without the express written permission of Sixnet.

Furthermore, the purchase of Sixnet products shall not be deemed to grant either directly or by implication, estoppels, or otherwise, any license under the copyrights, patents or patent applications of Sixnet, except for the normal non-exclusive, royalty-free license to use that arises by operation of laws in the sale of a product.

Sixnet, Inc.
2425 46th Avenue
Lachine, Quebec H8T 3C9
Canada
T +1 514 422 9110
F +1 514 422 3338
www.sixnet.com



Sixnet, Inc.
331 Ushers Road, Ballston Lake, NY 12019

FLEXIBLE. RELIABLE. POWERFUL.
T +1 518 877 5173 F +1 518 877 8346

IndustrialPro™ and MobilityPro™ Gateway Wireless Modems

BT Series Firmware Release Notes

TABLE OF CONTENTS

| | | |
|----------|---|-----------|
| 1 | Related Products | 4 |
| 2 | Upgrade Instructions | 5 |
| 2.1 | Normal update | 5 |
| 2.2 | Advanced update | 5 |
| 3 | Release Notes..... | 6 |
| 3.1 | Version 3.8.12 – Release Notes – April 04, 2012 | 6 |
| 3.2 | Version 3.8.11 – Release Notes – July 07, 2011..... | 6 |
| 3.3 | Version 3.8.10 – Release Notes – June 20, 2011 | 7 |
| 3.4 | Version 3.8.9 – Release Notes – February 15, 2011 | 9 |
| 3.5 | Version 3.8.8 – Release Notes – December 14, 2010..... | 10 |
| 3.6 | Version 3.8.7 – Release Notes – September 28, 2010..... | 12 |
| 3.7 | Version 3.8.6 – Release Notes – September 17, 2010..... | 13 |
| 3.8 | Version 3.8.5 – Release Notes – September 9, 2010..... | 14 |
| 3.9 | Version 3.8.4 – Release Notes – June 7, 2010 | 16 |
| 3.10 | Version 3.8.3 – Release Notes – February 18, 2010 | 18 |
| 3.11 | Version 3.8.2 – Release Notes – February 12, 2010 | 18 |
| 3.12 | Version 3.8.1 – Release Notes – January 11, 2010 | 19 |
| 3.13 | Version 3.8.0 – Release Notes – December 18, 2009..... | 20 |
| 4 | Support Information..... | 22 |



Sixnet, Inc.
331 Ushers Road, Ballston Lake, NY 12019

FLEXIBLE. RELIABLE. POWERFUL.
T +1 518 877 5173 F +1 518 877 8346

IndustrialPro™ and MobilityPro™ Gateway Wireless Modems

BT Series Firmware Release Notes

1 Related Products

This release applies to the following products:

- Legacy Industrial Wireless Modems (BT-4000 / BT-5000 Series):
 - CDMA 1xRTT: BT-4200, BT-5200
 - GSM/GPRS: BT-4400, BT-5400
 - CDMA EvDO: BT-4600, BT-4600A, BT-5600, BT-5600A
 - CDMA EvDO A: BT-4600A, BT-5600A
- **IndustrialPro™ Gateway** wireless modems (BT-6000 Series):
 - GSM/EDGE: BT-6401, BT-6401EB, BT-6421
 - CDMA EvDO A: BT-6600, BT-6601, BT-6601EB, BT-6621
 - GSM/HSPA: BT-6800, BT-6801, BT-6801EB, BT-6821
- **MobilityPro™ Gateway** wireless modems with GPS (BT-5000v2 Series):
 - CDMA EvDO A with GPS: BT-5600v2
 - GSM/HSPA with GPS: BT-5800v2



Sixnet, Inc.
331 Ushers Road, Ballston Lake, NY 12019

FLEXIBLE. RELIABLE. POWERFUL.
T +1 518 877 5173 F +1 518 877 8346

IndustrialPro™ and MobilityPro™ Gateway Wireless Modems

BT Series Firmware Release Notes

2 Upgrade Instructions

Table 1, below, provides a summary of the update procedure to follow depending on the firmware which currently resides in the modem (i.e. is being upgraded from).

| Model | Normal update | Advanced update required | Advanced update for IPsec support ¹ |
|-----------------------------|---------------|--------------------------|--|
| BT-4000 or BT-5000 series | >= 3.x | <= 2.x | N/A |
| BT-6000 or BT-5000v2 series | >= 3.6.0 | <= 3.4.9 | <= 3.6.1 |

Table 1 - Upgrade Process Matrix

2.1 Normal update

1. Use an Ethernet crossover cable (BT-4000/BT-5000), an Ethernet straight or crossover cable (BT-6000/BT-5000v2) or USB cable to connect modem and PC
2. Start BlueVue Device Manager (BVDM) and Click **Change connection type** and select **Modem IP**.
3. Type the modem IP address in the related field if needed
 - a. For Ethernet connection the default Modem IP is **192.168.0.1**
 - b. For USB connection, the default Modem IP is **192.168.111.1**
4. After the modem is detected, **click File > Configuration** and click **Firmware** tab
5. Select the update file you want to use, then click **Upgrade**
6. Wait for the firmware update to end and the modem to restart

2.2 Advanced update

Download the Advanced Update Package from the [Sixnet](#) website and follow the instructions in the "Advanced Firmware Update & Recovery Guide" (BT-4000/BT-5000) or "Advanced Firmware Update Procedure" (BT-6000 and BT-5000v2).

¹ In this case, an advanced upgrade is necessary to gain IPsec support. IPsec functionality is optional, so if IPsec support is not required, a basic upgrade can be performed instead, assuming that the minimum release is met as per the "Advanced update required" column.



Sixnet, Inc.
331 Ushers Road, Ballston Lake, NY 12019

FLEXIBLE. RELIABLE. POWERFUL.
T +1 518 877 5173 F +1 518 877 8346

IndustrialPro™ and MobilityPro™ Gateway Wireless Modems

BT Series Firmware Release Notes

3 Release Notes

3.1 Version 3.8.12 – Release Notes – April 04, 2012

The 3.8.12 release is intended for MobilityPro™ Gateway (BT-5600v2 and BT-5800v2) wireless modems with or without the USB Host extension.

Dependencies

| | Legacy modems BT-4000 / BT-5000 Series | | IndustrialPro™ and MobilityPro™ Gateway BT-5000v2 / BT-6000 Series | |
|--------------------|---|-----------------|---|-----------------|
| | Current Version | Minimum Version | Current Version | Minimum Version |
| Kernel | 2.6.15.1bt5 | 2.6.15.1bt5 | 2.6.21 #btw09 | 2.6.21 #btw03 |
| Boot Loader | 1.1.3bt10 | 1.1.3bt8 | 1.2.0-btw07 | 1.2.0-btw02 |
| File System | 3.0.0 | 2.0.0 | 3.0.0 | 3.0.0 |

Important Notes

- IPsec support (IndustrialPro™ and MobilityPro™ Gateway only) requires kernel 2.6.21 #btw04 or above.
- GRE tunnel support (IndustrialPro™ and MobilityPro™ Gateway only) requires kernel 2.6.21 #btw06 or above.
- USB Host support (MobilityPro™ Gateway only) requires kernel 2.6.21 #btw09 and u-boot 1.2.0-btw06.

New Features & Improvements

| ID | Subject | Description |
|------|---------------|---|
| 1256 | Network | Implemented TCP poll for Rastrac |
| 1255 | RF | HSPA RF hangs in IP Pass-thru mode at Telus lab tests |
| 1252 | Serial IP | AT&C3 -- DCD signal is decided by SIP TCP connection status |
| 1251 | BEP | BEP events not sent while the server is available |
| 1250 | BEP | ignition status is falsely reported on IO1 payload |
| 1249 | BEP | +BEVENT? not working in BEP MOM |
| 1248 | AT | Missing line feed character via serial port |
| 1243 | Events | Local Event Going to Wrong Destination |
| 8558 | Factory Tests | Expand the length for AT+BFACTINF command |
| 1241 | Fire Wall | IP source violation in IP pass-through mode |
| 1227 | GPS | Erroneous GPS GOS data reported – SNR filter as software solution |
| 1223 | RF | AT+BMDIAG to show override SPN name instead of network name |

3.2 Version 3.8.11 – Release Notes – July 07, 2011

The 3.8.11 release is intended for MobilityPro™ Gateway (BT-5600v2 and BT-5800v2) wireless modems with or without the USB Host extension.

Dependencies

| Legacy modems | IndustrialPro™ and MobilityPro™ Gateway |
|---------------|---|
|---------------|---|



Sixnet, Inc.
331 Ushers Road, Ballston Lake, NY 12019

FLEXIBLE. RELIABLE. POWERFUL.
T +1 518 877 5173 F +1 518 877 8346

IndustrialPro™ and MobilityPro™ Gateway Wireless Modems

BT Series Firmware Release Notes

| | BT-4000 / BT-5000 Series | | BT-5000v2 / BT-6000 Series | |
|--------------------|--------------------------|-----------------|-----------------------------|-----------------|
| | Current Version | Minimum Version | Current Version | Minimum Version |
| Kernel | 2.6.15.1bt5 | 2.6.15.1bt5 | 2.6.21 #btw09 | 2.6.21 #btw03 |
| Boot Loader | 1.1.3bt10 | 1.1.3bt8 | 1.2.0-btw07 | 1.2.0-btw02 |
| File System | 3.0.0 | 2.0.0 | 3.0.0 | 3.0.0 |

Important Notes

- IPsec support (IndustrialPro™ and MobilityPro™ Gateway only) requires kernel 2.6.21 #btw04 or above.
- GRE tunnel support (IndustrialPro™ and MobilityPro™ Gateway only) requires kernel 2.6.21 #btw06 or above.
- USB Host support (MobilityPro™ Gateway only) requires kernel 2.6.21 #btw09 and u-boot 1.2.0-btw06.

New Features & Improvements

| ID | Subject | Description |
|------|---------|---|
| 1240 | BEP | Wrong RSSI value reported in BEP events |

3.3 Version 3.8.10 – Release Notes – June 20, 2011

The 3.8.10 release is intended for MobilityPro™ Gateway (BT-5600v2 and BT-5800v2) wireless modems with or without the USB Host extension.

Dependencies

| | Legacy modems BT-4000 / BT-5000 Series | | IndustrialPro™ and MobilityPro™ Gateway BT-5000v2 / BT-6000 Series | |
|--------------------|---|-----------------|---|-----------------|
| | Current Version | Minimum Version | Current Version | Minimum Version |
| Kernel | 2.6.15.1bt5 | 2.6.15.1bt5 | 2.6.21 #btw09 | 2.6.21 #btw03 |
| Boot Loader | 1.1.3bt10 | 1.1.3bt8 | 1.2.0-btw06 | 1.2.0-btw02 |
| File System | 3.0.0 | 2.0.0 | 3.0.0 | 3.0.0 |

Important Notes

- IPsec support (IndustrialPro™ and MobilityPro™ Gateway only) requires kernel 2.6.21 #btw04 or above.
- GRE tunnel support (IndustrialPro™ and MobilityPro™ Gateway only) requires kernel 2.6.21 #btw06 or above.
- USB Host support (MobilityPro™ Gateway only) requires kernel 2.6.21 #btw09 and u-boot 1.2.0-btw06.



Sixnet, Inc.
331 Ushers Road, Ballston Lake, NY 12019

FLEXIBLE. RELIABLE. POWERFUL.
T +1 518 877 5173 F +1 518 877 8346

IndustrialPro™ and MobilityPro™ Gateway Wireless Modems

BT Series Firmware Release Notes

New Features & Improvements

| ID | Subject | Description |
|------|--------------|--|
| 1212 | Serial IP | Mobile Originated SIP :Add a modem ID(ESN/IMEI) as a header for each outgoing UDP packets |
| 1223 | RF | AT+BMDIAG and AT+BNSTAT to show override SPN name instead of network name for HSPA |
| 1219 | DNS | Added framework for DNS resolving, implemented for AT+BGPSDS, AT+BRPRDS, AT+BSIPDS, and AT+BIPREG |
| 1233 | Embedded APP | DNS support for embedded applications |
| 1225 | GPS | Add a new AT command for GPS elevation angle mask |
| 1235 | IO | Add a new AT command to adjust IO sampling interval |
| 1215 | RF | BT6400 Ping-keep-alive reset may keep the modem offline Add RF module reset as part of soft reset process |
| 1213 | RF | AT+BRFPON=0 takes too long to complete for CDMA during data session |
| 1218 | GPS | No GPS fix after intensive Ignition resets Added GPS module reset process in modem warm-reset process |
| 1224 | GPS | Losing GPS UDP report to local destination at ignition start-up |
| 1222 | RF | HSPA and CDMA RF power mode switched on/off multiple times causing modem reset |
| 1228 | RF | Turning off HSPA modem RF power causing long delay on RF event reporting |
| 1231 | Serial IP | Configuring the Serial IP on poll and push mode simultaneously may cause SIP to switch to command mode |
| 1234 | RF | WAN led remains on after Radio Power is turn off when using CDMA RF version MC5727 1.49 |
| 1236 | BEP | BEP packets to local host stopped when RF is powered off |



Sixnet, Inc.
331 Ushers Road, Ballston Lake, NY 12019

FLEXIBLE. RELIABLE. POWERFUL.
T +1 518 877 5173 F +1 518 877 8346

IndustrialPro™ and MobilityPro™ Gateway Wireless Modems

BT Series Firmware Release Notes

3.4 Version 3.8.9 – Release Notes – February 15, 2011

The 3.8.9 release is intended for MobilityPro™ Gateway (BT-5600v2 and BT-5800v2) wireless modems with or without the USB Host extension.

Dependencies

| | Legacy modems BT-4000 / BT-5000 Series | | IndustrialPro™ and MobilityPro™ Gateway BT-5000v2 / BT-6000 Series | |
|--------------------|---|-----------------|---|-----------------|
| | Current Version | Minimum Version | Current Version | Minimum Version |
| Kernel | 2.6.15.1bt5 | 2.6.15.1bt5 | 2.6.21 #btw09 | 2.6.21 #btw03 |
| Boot Loader | 1.1.3bt10 | 1.1.3bt8 | 1.2.0-btw06 | 1.2.0-btw02 |
| File System | 3.0.0 | 2.0.0 | 3.0.0 | 3.0.0 |

Important Notes

- IPsec support (IndustrialPro™ and MobilityPro™ Gateway only) requires kernel 2.6.21 #btw04 or above.
- GRE tunnel support (IndustrialPro™ and MobilityPro™ Gateway only) requires kernel 2.6.21 #btw06 or above.
- USB Host support (MobilityPro™ Gateway only) requires kernel 2.6.21 #btw09 and u-boot 1.2.0-btw06.

New Features & Improvements

| ID | Subject | Description |
|------|----------|---|
| 1191 | USB Host | Add USB Host to BT-5000v2 series. The feature requires the addition of a daughter card in the modem and of a USB Type A receptacle. |
| 1203 | USB Host | Add the AT+BUSBHOST=<mode> command to enable/disable and query the USB Host power |
| 1210 | USB Host | Add support for USB to Serial adapters. Include drivers for the two main devices: FTDI (ftdi_sio) and Prolific (pl2303) |
| 1211 | RF | Added workaround for Bell CDMA 01.67.01 call hangs on cold-start |



Sixnet, Inc.
331 Ushers Road, Ballston Lake, NY 12019

FLEXIBLE. RELIABLE. POWERFUL.
T +1 518 877 5173 F +1 518 877 8346

IndustrialPro™ and MobilityPro™ Gateway Wireless Modems

BT Series Firmware Release Notes

3.5 Version 3.8.8 – Release Notes – December 14, 2010

Dependencies

| | Legacy modems BT-4000 / BT-5000 Series | | IndustrialPro™ and MobilityPro™ Gateway BT-5000v2 / BT-6000 Series | |
|--------------------|---|-----------------|---|-----------------|
| | Current Version | Minimum Version | Current Version | Minimum Version |
| Kernel | 2.6.15.1bt5 | 2.6.15.1bt5 | 2.6.21 #btw08 | 2.6.21 #btw03 |
| Boot Loader | 1.1.3bt10 | 1.1.3bt8 | 1.2.0-btw05 | 1.2.0-btw02 |
| File System | 3.0.0 | 2.0.0 | 3.0.0 | 3.0.0 |

Important Notes

- IPsec support (IndustrialPro™ and MobilityPro™ Gateway only) requires kernel 2.6.21 #btw04 or above.
- GRE tunnel support (IndustrialPro™ and MobilityPro™ Gateway only) requires kernel 2.6.21 #btw06 or above.

New Features & Improvements

| ID | Subject | Description |
|----------------------|----------------------|--|
| 646 | IP routing | Double the number of IP forwarding ports to 40 ports (AT+BIPFWD) |
| 1071 1178 | Serial IP | Add the AT+BSIPMO (Serial IP Mobile Originated settings) command to allow setting up a timer used for keeping the Serial IP connection alive. The timer is used for TCP Keep-Alive timer setting or for periodically sending an empty UDP packet to keep firewalls open. When configured with a non-null timer value the modem is not waiting for data to be present on the serial port to establish a connection. |
| 1185 | BEP | Add network information to RF2 payload for GSM modems The BEP RF2 Carrier information now contains the GSM operator name (see AT+BMDIAG?) for GSM modems (GPRS/EDGE/HSPA). For CDMA modems, the field contains the programmed carrier name. |
| 1189 | IP Forwarding | Add the AT+BIPFWDI=<index>,<interface> command to set/query the interface of the incoming IP packets to forward. With this command, the modem can now perform IP forwarding on packets arriving on the Ethernet(1), USB(2) or WAN(3 - default) interface. |



Sixnet, Inc.
331 Ushers Road, Ballston Lake, NY 12019

FLEXIBLE. RELIABLE. POWERFUL.
T +1 518 877 5173 F +1 518 877 8346

IndustrialPro™ and MobilityPro™ Gateway Wireless Modems

BT Series Firmware Release Notes

Fixed Issues

| ID | Subject | Description |
|------|---------|---|
| 1179 | LAN | DNS settings are now updated into the DHCP configuration even when it changes during a connection. DHCP lease time shall be configured for the DHCP client to get the updated DNS settings. |
| 1182 | RF | The RF power off state (available via AT+BRFPON=0 on BT-4600A/BT-5600A, BT-6000 series, and BT-5000v2 series) is now persistent after a reboot (broken in 3.8.5). |
| 1184 | BEP | The MI3 payload was missing RF and GPS information when associated with the IGN ON trigger. |
| 1190 | RF | RF Tx power can now be disabled via AT+BRFPON=0 on BT-6600 series and BT-5600v2 without triggering a modem reset. |



Sixnet, Inc.
331 Ushers Road, Ballston Lake, NY 12019

FLEXIBLE. RELIABLE. POWERFUL.
T +1 518 877 5173 F +1 518 877 8346

IndustrialPro™ and MobilityPro™ Gateway Wireless Modems

BT Series Firmware Release Notes

3.6 Version 3.8.7 – Release Notes – September 28, 2010

Dependencies

| | Legacy modems BT-4000 / BT-5000 Series | | IndustrialPro™ and MobilityPro™ Gateway BT-5000v2 / BT-6000 Series | |
|--------------------|---|--------------------|---|-----------------|
| | Current Version | Minimum Version | Current Version | Minimum Version |
| Kernel | 2.6.15.1bt5 | 2.6.15.1bt5 | 2.6.21 #btw07 | 2.6.21 #btw03 |
| Boot Loader | 1.1.3bt10 | 1.1.3bt8 | 1.2.0-btw04 | 1.2.0-btw02 |
| File System | 3.0.0 | 2.0.0 | 3.0.0 | 3.0.0 |

Important Notes

- IPsec support (IndustrialPro™ and MobilityPro™ Gateway only) requires kernel 2.6.21 #btw04 or above.
- GRE tunnel support (IndustrialPro™ and MobilityPro™ Gateway only) requires kernel 2.6.21 #btw06 or above.

Fixed Issues

| ID | Subject | Description |
|-------------|---------------|--|
| 1180 | WAN | EvDO Rel. 0: Cannot connect in Always-on The RF Power status test intended for EvDO A modems was preventing BT-4600 and BT-5600 modems to connect when in Always-on mode. |
| 1181 | Events | Modem fails to send raw NMEA GPS using AT+BEVRPR. |



Sixnet, Inc.
331 Ushers Road, Ballston Lake, NY 12019

FLEXIBLE. RELIABLE. POWERFUL.
T +1 518 877 5173 F +1 518 877 8346

IndustrialPro™ and MobilityPro™ Gateway Wireless Modems

BT Series Firmware Release Notes

3.7 Version 3.8.6 – Release Notes – September 17, 2010

Dependencies

| | Legacy modems BT-4000 / BT-5000 Series | | IndustrialPro™ and MobilityPro™ Gateway BT-5000v2 / BT-6000 Series | |
|-------------|---|--------------------|---|-----------------|
| | Current Version | Minimum Version | Current Version | Minimum Version |
| Kernel | 2.6.15.1bt5 | 2.6.15.1bt5 | 2.6.21 #btw07 | 2.6.21 #btw03 |
| Boot Loader | 1.1.3bt10 | 1.1.3bt8 | 1.2.0-btw04 | 1.2.0-btw02 |
| File System | 3.0.0 | 2.0.0 | 3.0.0 | 3.0.0 |

Important Notes

- IPsec support (IndustrialPro™ and MobilityPro™ Gateway only) requires kernel 2.6.21 #btw04 or above.
- GRE tunnel support (IndustrialPro™ and MobilityPro™ Gateway only) requires kernel 2.6.21 #btw06 or above.

Fixed Issues

| ID | Subject | Description |
|------|---------|--|
| 1176 | AT | In on-demand mode, requesting a manual disconnection while the modem is being disconnected due to RF conditions may cause a modem restart. |



Sixnet, Inc.
331 Ushers Road, Ballston Lake, NY 12019

FLEXIBLE. RELIABLE. POWERFUL.
T +1 518 877 5173 F +1 518 877 8346

IndustrialPro™ and MobilityPro™ Gateway Wireless Modems

BT Series Firmware Release Notes

3.8 Version 3.8.5 – Release Notes – September 9, 2010

Dependencies

| | Legacy modems BT-4000 / BT-5000 Series | | IndustrialPro™ and MobilityPro™ Gateway BT-5000v2 / BT-6000 Series | |
|--------------------|---|-----------------|---|-----------------|
| | Current Version | Minimum Version | Current Version | Minimum Version |
| Kernel | 2.6.15.1bt5 | 2.6.15.1bt5 | 2.6.21 #btw07 | 2.6.21 #btw03 |
| Boot Loader | 1.1.3bt10 | 1.1.3bt8 | 1.2.0-btw04 | 1.2.0-btw02 |
| File System | 3.0.0 | 2.0.0 | 3.0.0 | 3.0.0 |

Important Notes

- IPsec support (IndustrialPro™ and MobilityPro™ Gateway only) requires kernel 2.6.21 #btw04 or above.
- GRE tunnel support (IndustrialPro™ and MobilityPro™ Gateway only) requires kernel 2.6.21 #btw06 or above.

New Features & Improvements

| ID | Subject | Description |
|--------------|-------------|--|
| 956 | Events | Increase the number of configurable events (AT+BEVENT) to 63. |
| 1157 | GPS | Add the capability to log received GPS fixes (AT+BGPSLOG). When enabled, the GPS logs are part of the modem log files. |
| 1161 | GPS | Periodically save GPS odometer value in non-volatile memory independently of IGN state. |
| 1158 | RF | Report the RF module type in AT11. Report PRI (CDMA EvDO.A and HSPA) and PRL Region (HSPA) in AT11. |
| 1150 | RF (EVDO.A) | Add support for MC5728V RF module |
| 1160 1169 | RF (HSPA) | Add Sasktel and MTS to automatic HSPA configuration. Automatic GSM/EDGE/HSPA configuration occurs when the modem is reset to its factory configuration (AT&F) according to the installed SIM card. This feature may be restricted on some modems. |



Sixnet, Inc.
331 Ushers Road, Ballston Lake, NY 12019

FLEXIBLE. RELIABLE. POWERFUL.
T +1 518 877 5173 F +1 518 877 8346

IndustrialPro™ and MobilityPro™ Gateway Wireless Modems

BT Series Firmware Release Notes

Fixed Issues

| ID | Subject | Description |
|------|-----------------|---|
| 1155 | AT | An incorrect IP settings in AT+BIPREG was crashing the modem |
| 1156 | AT | Modem failed to properly close the telnet to ports 5070/6070 when the peer terminates the connection. |
| 1159 | AT | AT+COPN? was returning ERROR since the response is too long to fit in the AT command response buffer. The results may now be obtained by issuing successive AT+COPN commands. |
| 1162 | AT | Modem may restart randomly when AT+BMDIAG? is automatically issued at very high frequency. |
| 1151 | Events | Legacy modems (BT-4000/BT-5000) had an invalid device ID in BEP messages. |
| 1153 | Events | AT command response was restricted to short strings. |
| 1165 | Events | Reduce latency to send first BEP message |
| 1167 | Events | IMOM (Initial Mobile Originated Management) Server errors are logged too frequently. IMOM connection to a remote server is now only attempted every 30 minutes. |
| 1154 | IP Registration | The IP registration message sent by GSM modems had an extra white space. |
| 1166 | IP Routing | Incorrect LAN routing when in On-Demand mode and not connected to WAN. |
| 1152 | Partner Apps | The application was occasionally failing to start. |
| 1164 | RF | Add WD to recover from a failure to connect in on-demand mode. |
| 1048 | RF (HSPA) | Show the HSPA packet session status in the RF state of AT+BMDIAG? and AT+BNSTAT? of HSPA modems. |
| 1103 | RF (HSPA) | Re-enabling the HSPA RF module transmit (AT+BRFPON=1) is no longer triggering a modem reset. |
| 1163 | RF (HSPA) | Modem to report only the RSSI of the active cell (HSPA). |



Sixnet, Inc.
331 Ushers Road, Ballston Lake, NY 12019

FLEXIBLE. RELIABLE. POWERFUL.
T +1 518 877 5173 F +1 518 877 8346

IndustrialPro™ and MobilityPro™ Gateway Wireless Modems

BT Series Firmware Release Notes

3.9 Version 3.8.4 – Release Notes – June 7, 2010

Dependencies

| | Legacy modems BT-4000 / BT-5000 Series | | IndustrialPro™ and MobilityPro™ Gateway BT-5000v2 / BT-6000 Series | |
|--------------------|---|-----------------|---|-----------------|
| | Current Version | Minimum Version | Current Version | Minimum Version |
| Kernel | 2.6.15.1bt5 | 2.6.15.1bt5 | 2.6.21 #btw07 | 2.6.21 #btw03 |
| Boot Loader | 1.1.3bt10 | 1.1.3bt8 | 1.2.0-btw04 | 1.2.0-btw02 |
| File System | 3.0.0 | 2.0.0 | 3.0.0 | 3.0.0 |

Important Notes

- IPsec support (IndustrialPro™ and MobilityPro™ Gateway only) requires kernel 2.6.21 #btw04 or above.
- GRE tunnel support (IndustrialPro™ and MobilityPro™ Gateway only) requires kernel 2.6.21 #btw06 or above.

New Features & Improvements

| ID | Subject | Description |
|------|-------------|---|
| 1023 | Modem Time | Synchronize modem time on NTP, GPS or CELL Add the AT+BMTIME command to select the time source, the AT+BNTTP to select NTP servers and the AT+BNTPST command to monitor the NTP client. |
| 1042 | GRE Tunnels | GRE Tunnel support Add the AT+BGRETUN, AT+BGREOPT, AT+BGREKEY, AT+BGREMR, AT+BGREDI, AT+BMCASTR, AT+BSROUTE AT commands to support GRE tunneling. This feature is available on BT-6000 and BT-5600v2/BT-5800v2 only with kernel 2.6.21 btw#06 or above. |
| 1043 | GPS | Specific NMEA sentence mask per destination The AT+BGPSRP allows to set a specific NMEA message mask per GPS destination (IP1, IP2 and Serial). |
| 1044 | GPS | Specific reporting timer per destination The AT+BGPSRP allows to set a specific reporting timer per GPS destination (IP1, IP2 and Serial). |
| 1116 | Events | Add capability to log BEP events (AT+BEVLOG). |
| 1117 | Events | Add capability to purge stored BEP events (AT+BSFMRM=1) Note: The modem needs to be reset once the command is issued. |
| 1118 | Events | Report Store and Forward memory status (AT+BSFMST?) The AT+BSFMST? command reports the number of used and free memory blocks as well as the number of stored events per BEP destination. |
| 1142 | Security | Serial port AT command protection Access to AT command can now be password protected the same way as access from LAN and/or WAN with the AT+BRPSWD command. |



Sixnet, Inc.
331 Ushers Road, Ballston Lake, NY 12019

FLEXIBLE. RELIABLE. POWERFUL.
T +1 518 877 5173 F +1 518 877 8346

IndustrialPro™ and MobilityPro™ Gateway Wireless Modems

BT Series Firmware Release Notes

Fixed Issues

| ID | Subject | Description |
|------|-------------|---|
| 898 | WAN | Traffic from USB causes WAN to disconnect when in IP pass-through |
| 902 | Events | Incorrect event ACK in UDP causes reporting destination to change This was an issue when the BEP server did not use the same port for source and destination. |
| 1074 | Events | Modem does not report signal strength in EVDO-only mode |
| 1081 | GPS | GPS sensitivity Improve GPS stationary detection, especially for Copernicus firmware 3.02 and Copernicus II firmware 1.04. |
| 1093 | Events | BEP: BT-5400 reports 0 as device ID |
| 1091 | GPS | Close GPS port 9999. The modem GPS server port may be re-opened with AT+BGPSSV |
| 1119 | DUN | Dial-up Networking (DUN) PC failed to connect after a few connect/disconnect cycles. |
| 1120 | Apps | Partner apps: No access to localhost when in IP pass-through |
| 1122 | | Support for BT-4600/BT-5600 (EVDO rel. 0) Re-introduce support for those models (broken in 3.8.3) |
| 1123 | Apps | Internal connections to tcp:5070/tcp:6070 when AT password is enabled |
| 1124 | Events | BEP RSSI value in RF2 payload The value is now coded according to specification (positive in RF2 and negative in RF1). |
| 1127 | GPS | GPS reporting to IP destination faster than the value specified in the reporting timer of AT+BGPSPR. |
| 1128 | Events | MOM: Modem jobs fail when configured with UDP |
| 1129 | Apps | Partner apps: last reserved port not configured |
| 1131 | Serial IP | Listening server hangs when client disconnects |
| 1133 | Events | MOM: multiple re-transmissions of TCP/IP BEP packets |
| 1134 | AT | AT commands: timeout and out of sequence From time to time the modem AT interface fails until the modem is restarted. |
| 1135 | Events | +BEVENT: "WAN" signal trigger is missing The WAN signal trigger of AT+BEVENT was documented but not implemented. |
| 1140 | Apps | Partner apps: Frequent app enabling/disabling breaks AT commands |
| 1141 | WAN | +BMDIAG does not show correct WAN IP address The WAN IP address in AT+BMDIAG is occasionally prefixed with the string 'ppp'. When this happens, AT+BIPINF fails (returns ERROR) and the modem cannot communicate on its WAN interface. |
| 1144 | Events | +BEVAIS value2 parsed as an integer instead of a float Correctly parse the two values of the comparison expression. |
| 1146 | Diagnostics | EVDO modems fail pass-through to RF diagnostic port (DM) |
| 1148 | AT | ATO occasionally does not return modem to Serial IP mode |
| 1149 | AT | Long AT responses not entirely written on serial port |



Sixnet, Inc.
331 Ushers Road, Ballston Lake, NY 12019

FLEXIBLE. RELIABLE. POWERFUL.
T +1 518 877 5173 F +1 518 877 8346

IndustrialPro™ and MobilityPro™ Gateway Wireless Modems

BT Series Firmware Release Notes

3.10 Version 3.8.3 – Release Notes – February 18, 2010

Dependencies

Unchanged from 3.8.0, see below.

Fixed Issues

| ID | Subject | Description |
|------|-----------------|--|
| 1113 | IP pass-through | Occasionally, when first acquiring the WAN IP address or when the WAN IP address gets re-negotiated, the modem may fail to configure the interface assigned to IP pass-through with the WAN IP until the modem resets. |

3.11 Version 3.8.2 – Release Notes – February 12, 2010

Dependencies

Unchanged from 3.8.0, see below.

New Features & Improvements

| ID | Subject | Description |
|------|---------|--|
| 1053 | HSPA | HSPA automatic configuration When the modem is reset to factory configuration (AT&F or Action > Reset Modem in BVDM), the connection dial string, username, password and APN are automatically set according to the SIM card settings. |

Fixed Issues

| ID | Subject | Description |
|------|---------------|---|
| 1032 | Serial port | Serial port not reset to configuration settings after BVDM disconnects. |
| 1037 | Events | AT+BEVGSS syntax should be verified |
| 1039 | Serial IP | IP->Serial and Serial->IP values inverted in SIP diag |
| 1092 | RF | EVDO A modems may fail to connect (Verizon and Sprint only). |
| 1097 | RF | WAN LED does not blink to indicate WAN activity |
| 1098 | RF | Modem failed to log RF Diagnostic information (DM) in QxDm |
| 1099 | Configuration | Modem loses its password after upgrade |
| 1102 | RF | HSPA: Manual network selection (+COPS) is missing parameter |
| 1107 | AT | Frequent +BMDIAG/+BNSTAT resets modem |
| 1108 | Configuration | Firmware upgrade sets MTU to zero |

Known issues

Unchanged from 3.8.0, see below.



Sixnet, Inc.
331 Ushers Road, Ballston Lake, NY 12019

FLEXIBLE. RELIABLE. POWERFUL.
T +1 518 877 5173 F +1 518 877 8346

IndustrialPro™ and MobilityPro™ Gateway Wireless Modems

BT Series Firmware Release Notes

3.12 Version 3.8.1 – Release Notes – January 11, 2010

Dependencies

Unchanged from 3.8.0, see below.

Fixed Issues

| ID | Subject | Description |
|------|---------|---|
| 1082 | AT | Frequent connections/disconnections from telnet AT commands reset modem. |
| 1087 | Events | MI2 and MI3 PRL and GPS version fields are missing for some modem models. |
| 1089 | Events | Information is missing in initial ignition ON BEP message. |
| 1088 | RF | BT-6400 series modems fail to report EDGE service when available. |
| 1092 | RF | EVDO A modems may fail to connect (Verizon and Sprint only). |
| 1090 | Startup | Improve hardware verification (Ethernet and USB) at modem startup. |
| 1100 | Startup | Improve cold weather modem startup. |

Known issues

Unchanged from 3.8.0, see below.



Sixnet, Inc.
331 Ushers Road, Ballston Lake, NY 12019

FLEXIBLE. RELIABLE. POWERFUL.
T +1 518 877 5173 F +1 518 877 8346

IndustrialPro™ and MobilityPro™ Gateway Wireless Modems

BT Series Firmware Release Notes

3.13 Version 3.8.0 – Release Notes – December 18, 2009

Dependencies

| | Legacy modems BT-4000 / BT-5000 Series | | IndustrialPro™ and MobilityPro™ Gateway BT-5000v2 / BT-6000 Series | |
|--------------------|---|-----------------|---|----------------------------|
| | Current Version | Minimum Version | Current Version | Minimum Version |
| Kernel | 2.6.15.1bt5 | 2.6.15.1bt5 | 2.6.21 #btw06 | 2.6.21 #btw02 ² |
| Boot Loader | 1.1.3bt10 | 1.1.3bt8 | 1.2.0-btw04 | 1.2.0-btw02 |
| File System | 3.0.0 | 2.0.0 | 3.0.0 | 3.0.0 |

Important Notes

- Release 3.6.2 added IPsec functionality to the BT-5000v2 and BT-6000 series modems. If upgrading from a version prior to 3.6.2, an advanced upgrade is necessary to enable IPsec support.

New Features & Improvements

| ID | Subject | Description |
|------|------------------|---|
| 674 | Firmware upgrade | Modem initiated upgrade package download The AT+BWGET can be used to download an upgrade package from an FTP or HTTP site. |
| 1014 | Events | WAN event added to BEP The WAN event (see AT+BEVENT) can be used to signal when the modem has a WAN IP address and when it changes. |
| 1015 | Events | Modem Originated Management Destination type 3 (MOM) can now be used to initiate management action from the modem. See AT+BRPRDS/AT+BEVRPR/AT+BEVENT. This feature is meant to operate with BlueVue Group (release 2.1.80) |
| 1017 | Events | Add new BEP payloads: MI2, MI3, RF2, IP1 Those new message payloads can be used to report status information to a management server. |
| 1018 | Events | Add new BEP payload: AU1 This new BEP payload can be used authenticate BEP messages. |
| 1019 | Events | Add new BEP payload: AC1 This new BEP payload can be used to exchange AT commands and responses between a management server (BVG) and the modem. |
| 1027 | GPS | Synchronize modem time on GPS: AT+BGPSDT |

² The “minimum” kernel version of 2.6.21 #btw02 does not support IPsec. If IPsec is required, an advanced upgrade should be performed to upgrade the kernel to 2.6.21 #btw04 or above.



Sixnet, Inc.
331 Ushers Road, Ballston Lake, NY 12019

FLEXIBLE. RELIABLE. POWERFUL.
T +1 518 877 5173 F +1 518 877 8346

IndustrialPro™ and MobilityPro™ Gateway Wireless Modems

BT Series Firmware Release Notes

Fixed Issues

| ID | Subject | Description |
|------|------------|--|
| 1028 | Serial IP | Modem fails to transfer files via Serial IP |
| 1035 | IPSEC | AT+BIPSSN? does not display the remote subnet configuration |
| 1040 | RF | RF diagnostic pass-through via serial fails |
| 1054 | FTP | The FTP server was failing when enabled multiple times. |
| 1055 | DHCP | In IP pass-through, the DHCP lease time is reduced to 30 seconds until the WAN IP is available and assigned to the local interface. The configured DHCP lease time is then used. |
| 1056 | GPS/Events | GPS/BEP UDP destinations connects/disconnects every 30 seconds This occurred when +BSYNC was used and no ACK messages were received. |
| 1057 | RF | HSPA: Intermittent high latency and ping packet loss |
| 1073 | AT | AT+BIPINF returns ERROR |
| 1077 | GPS | GPS fix not reported |
| 1079 | UDP | Intermittent high latency and loss of UDP packets |
| 1080 | RF | HSPA: MCC reported instead of MNC |

Known Issues

| ID | Subject | Description |
|-----|------------|---|
| 917 | Activation | New modems on Sprint now utilize OMA-DM instead of IOTA for provisioning, resulting in an error when the AT!IOTASTART command is issued. OMA-DM can be started with AT!dmdc=2 instead. This change requires BlueVue Device Manager 1.7.9 for automatic activation. |
| 880 | Activation | A bug in the Sierra Wireless MC5727 module returns ERROR during activation when in fact the activation may have been successful. A workaround is available in BlueVue Device Manager 1.7.9. |
| 966 | WAN LED | The WAN LED on BT-5800v2 and BT-6800 series may not indicate the connection status when the RF Transmit has been disabled and then re-enabled using AT+BRFPON. This issue only exists with RF module firmware: K1_0_2_8AP. |



Sixnet, Inc.
331 Ushers Road, Ballston Lake, NY 12019

FLEXIBLE. RELIABLE. POWERFUL.
T +1 518 877 5173 F +1 518 877 8346

IndustrialPro™ and MobilityPro™ Gateway Wireless Modems

BT Series Firmware Release Notes

4 Support Information

Visit the Industrial Wireless Product Support section of Sixnet website to download product manuals, software updates and modem firmware updates.

US & Canada +1-877-432-9908

International +1-518-877-5173

Email support@sixnet.com

Website <http://www.sixnet.com>



Sixnet, Inc.
331 Ushers Road, Ballston Lake, NY 12019

FLEXIBLE. RELIABLE. POWERFUL.
T +1 518 877 5173 F +1 518 877 8346