

N-Tron® Series NT5000 Gigabit Managed Ethernet Switches

Firmware Release Notes | February 2025 LP1195 | Revision E Through Version 1.3.5

COPYRIGHT

© 2025 Red Lion Controls, Inc. All Rights Reserved. The terms Red Lion, the Red Lion logo, N-Tron, N-View and N-Ring are trademarks or registered trademarks of Red Lion Controls. All other marks are the property of their respective owners.

Corporate Headquarters Red Lion Controls, Inc. 1750 5th Avenue York, PA 17403

CONTACT INFORMATION:

AMERICAS

Inside US: +1 (877) 432-9908 Outside US: +1 (717) 767-6511 **Hours:** 8 am-6 pm Eastern Standard Time (UTC/GMT -5 hours)

ASIA-PACIFIC

Shanghai, P.R. China: +86 21-6113-3688 x767 Hours: 9 am-6 pm China Standard Time (UTC/GMT +8 hours)

EUROPE

Netherlands: +31 33-4723-225 France: +33 (0) 1 84 88 75 25 Germany: +49 (0) 1 89 5795-9421 UK: +44 (0) 20 3868 0909 Hours: 9 am-5 pm Central European Time (UTC/GMT +1 hour)

Website: <u>www.redlion.net</u> Support: <u>support.redlion.net</u>

Table of Contents

NT5000 Firmware Release Notes	.1
Document Change History	1
NT5000 System Firmware	.3
Firmware Release Version 1.3.4 to 1.3.5 Delta	3
Previous Versions	.5
Firmware Release Version 1.3.2 to 1.3.4 Delta	5
Firmware Release Version 1.2.3 to 1.3.2 Delta	5
Firmware Release Version 1.1.6 to 1.2.3 Delta	5
Firmware Release Version 1.1.5 to 1.1.6 Delta	6

REDLION[®]

Table of Contents

NT5000 Firmware Release Notes

Document Change History

VERSION	DATE	DESCRIPTION
1.3.5	February 2025	Release 1.3.5 System Firmware
1.3.4	September 17, 2024	Release 1.3.4 System Firmware
1.3.2	April 2, 2024	Release 1.3.2 System Firmware
1.2.3	November 2023	Release 1.2.3 System Firmware
1.1.6	February 2023	Release 1.1.6 System Firmware

NT5000 Gigabit Managed Ethernet Switches

REDLION®

NT5000 System Firmware

Firmware Release Version 1.3.4 to 1.3.5 Delta

General

- Correct an issue when setting PTP filters on high port count devices.
- Corrected UI issues on the RADIUS page.

Previous Versions

Firmware Release Version 1.3.2 to 1.3.4 Delta

General

- Corrected issue with removing IP routes
- Corrected issue that would prevent importing or exporting very large files

DHCP (Dynamic Host Configuration Protocol)

- Corrected issue where IP by Port, DHCP settings are not correctly preserved through a restart
- Corrected issue with special characters in DHCP option 61 client ID
- Removed unsupported DHCP Option 12 interface elements

Firmware Release Version 1.2.3 to 1.3.2 Delta

General

- Refined privilege page descriptions
- Refined CLI and GUI page text
- Various help text improvements

Behavior

- Updated delete functionality to notify the user if the delete button is activated without selecting anything to delete
- Corrected CLI bootup options

N-View™

• Corrected N-View to properly report N-Ring[™] manager status

Libraries

• Updated various open source libraries

Firmware Release Version 1.1.6 to 1.2.3 Delta

Feature Enhancements

- N-Ring[™] Manager
- DHCP Server with option 61 and Relay Agent with option 82
- Syslog support for up to 5 collectors

Web UI Improvements

• Added the ability to export the event log via the web user interface

- Added the ability to make a copy of the config file(s)
- Added a description for the notification column in the help of the LLDP ports page
- Added gateway to the IP interfaces table
- Changed the text on the User Lockout webpage from "Mode" to "Enabled"
- Changed the Ports settings page to show the correct PVID when VLANs have been removed
- Changed the text in Ports under Port Security from "Mode" to "Enabled" and changed the dropdown selection to a green slider
- Changed the Alarms History to display the most recent alarm event at the top of the list
- Product Info page no longer displays bootloader as it is part of the firmware
- Eliminated the VLAN learning menu tab when the user does not have VLAN privileges
- Eliminated duplicate UI errors that occur when port config privileges are removed
- Added SSL certificate status to the HTTPS webpage
- Added the ability to upload HTTPS certificates from the web UI
- Corrected timeout error in HTTPs file transfer process. If errors are encountered while updating the NT5000 from 1.1.6 to 1.2.3, the use of TFTP or N-View[™] 2 to update the firmware is recommended.

SNMP Enhancement

• Added support for voltage and temperature

IGMP

- Corrected issue when multiple switches erroneously report status as the active querier
- Changed IGMP fast leave to active by default
- Updated IGMP CLI command to show rFilter port status

RADIUS

• Added RADIUS tags for setting user specific privileges

Firmware Release Version 1.1.5 to 1.1.6 Delta

- Resolved momentary drop in traffic during fast boot
- Repositioned error flags on even and odd ports on logical view to avoid overlap
- Resolved issue with DHCP IP address in N-View[™] frames
- Fixed size of factory default warning dialog
- Fixed quick setup page to resolve issue that would not allow some buttons to be pressed or help dialog to display
- Updated help text